





Facial hair standard for working in potentially hazardous atmospheres

Examples of **acceptable** facial hair include:

| | | |
|---|--|---|
|  |  |  |
| clean shaven | sideburns that do not extend below the bottom of the ear | neatly trimmed moustache that does not extend below the corners of the mouth |

Examples of **unacceptable** facial hair include:



In the event that a hazardous atmospheric condition is present, respiratory protection must be worn, and a clean shaven face with only minimal sideburns or moustache is necessary to ensure a proper fitting face mask. Due to the hazardous nature of hydrocarbons, petroleum industry workers must always be prepared to utilize a breathing apparatus. Refer to the examples above or consult your Suncor supervisor if you require clarity about what is deemed acceptable facial hair at Suncor.



OCCUPATIONAL HEALTH AND SAFETY ACT

OCCUPATIONAL HEALTH AND SAFETY CODE

2009

Effective facial seal

250(1) An employer must ensure that respiratory protective equipment that depends on an effective facial seal for its safe use is correctly fit tested and tested in accordance with

- (a) CSA Standard Z94.4-02, *Selection, Use and Care of Respirators*, or
- (b) a method approved by a Director of Occupational Hygiene.

250(2) An employer must ensure that, if a worker is or may be required to wear respiratory protective equipment and the effectiveness of the equipment depends on an effective facial seal, the worker is clean shaven where the face piece of the equipment seals to the skin of the face.